Pella Service Parts Catalog

Original Pella® Multi-Purpose Window
1950 - 1966

Contents

Sash
Weatherstrip. 3

Frame
Weatherstrip. 3

Hardware
Crank. 3
Handle. 3
Arm Shoe 3
Breathers and Plugs 3
Roto Operator 5

Muntins
Muntin Hardware. 6

Flat Screen 7


Double Glazing Panel (DGP) parts and accessories can be found in the Hinged Glass Panel parts catalog

Rev. 10/19/2017

Original Pella® Multi-Purpose

index


	Part Number	Catalog Category	Catalog Subcategory
MP Vent Sash 1953-1955	Replacement sash are no longer available.		




MP Vent Sash 1956-1958	Replacement sash are no longer available.		




MP Vent Sash 1959-1961	Replacement sash are no longer available.		




MP Vent Sash 1962-1966	Replacement sash are no longer available.		



	Part Number	Catalog Category	Catalog Subcategory
 MP Sash Weatherstrip 3/1950-1958	No Longer Available		
 MP Sash Weatherstrip 1962-1963	No Longer Available		
 MP Jamb Weatherstrip Note: Use to replace 1959-4/1961 design Weatherstrip. Also used as MP sash weatherstrip from 1959 -1961. 5/1961-1963	No Longer Available		
 MP Jamb Weatherstrip 1962-1963	No Longer Available		
 MP Roto Nylon Cover –Reverse (shown) –Normal 1963-1966	No Longer Available		
 Bronze Crank 1953-1966	0C080002	Casement, Awning, LA, DH Fix	Obsolete CM Hardware
 MP/DC Lock Handle 1953-1966	No Longer Available		
 MP Nylon Sector Arm Shoe 1963-1996			
 Sash Breather - (box 100) 1950-1996			
 Sash Breather Plug - (box 500) 1950-1996	No Longer Available		

	Part Number	Catalog Category	Catalog Subcategory
 MP Aluminum Bar Operator Knob 1953-1962	No Longer Available		
 MP Nylon bar Operator Knob 1963-1966	No Longer Available		
 MP Pivot Plate Assembly Visible Glass Height: –LH - 10-1/4" –LH - 14-1/4" –LH - 18-1/4" –LH - 22-1/4" –LH - 26-1/4" –RH - (Use same rule as above) 1956-1966	No Longer Available		
 MP Pivot Arm and Slide Assembly Visible Glass Height: –LH - 10-1/4" –LH - 14-1/4" –LH - 16-1/4" –LH - 18-1/4" –LH - 22-1/4" –LH - 26-1/4" –RH - (Use same rule as above) 1956-1966	No Longer Available		
 MP Transom Catch Assembly 1963-1966	No Longer Available		
 MP Sash Catch 6/1964-1966	No Longer Available		
 MP Glide Lock Assembly –Normal (shown) 1963-1966	No Longer Available		







	Part Number	Catalog Category	Catalog Subcategory
MP Roto Operator Repair Kit - (box 5) –Reverse –Normal (shown) 2/1959-1962	No Longer Available		
MP Roto Operator Assembly –Reverse –Normal (shown) 1963-1966	No Longer Available		
MP Bar Operator Assembly 18-5/8" –Reverse –Normal (shown) 1963-1966	No Longer Available		
MP Bar Operator Assembly 17-5/8" –Reverse –Normal (shown) 12/1953-1962	No Longer Available		
MP Bar Operator Assembly 20-5/8" –Reverse –Normal (shown) 12/1953-1962	No Longer Available		
MP Bar Operator Arm Lock Support 12/1953-1966	No Longer Available		
MP Lock Rose 6/1964-1966	No Longer Available		

	Part Number	Catalog Category	Catalog Subcategory
MP Regular Muntin Assembly 1950-1962 1963-1966	No Longer Available		






Muntin Clip –(box 100) –(box 10) 1958-1966	 0CFP0000 0CFP0001	Muntin Hardware and Parts	Muntin Hardware




Classic Muntin Tack –(box 1000) –(box 10) 1958-1966	 0B0K0000 0B0K0001	Muntin Hardware and Parts	Muntin Hardware

MP Diamond Muntin Assembly 1950-1962 1963-1966	No Longer Available		





Bullet Catch - (box 100) 1958-1966			



	Part Number	Catalog Category	Catalog Subcategory
MP Screen 1963-1966 Note: Screens are no longer available from Pella. Recommended having new screens manufactural by local screen vendors.			



MP Screen 1950-1962 Note: Screens are no longer available from Pella. Recommended having new screens manufactural by local screen vendors.			