Pella Service Parts Catalog

Original Pella®
Wood/Clad Double-Hung

1964 - 1983

Contents

Sash
Hardware . . . 2
Cladding . . . 2
Weatherstrip . . . 3


Frame
Weatherstrip . . . 3
Plugs . . . 3
Bumper . . . 3
Jamb Booster Spring . . . 4
Balance Cord . . . 4
Balance Plate Assembly . . . 4
Balance Pully . . . 4
Springs . . . 4
Jambliner . . . 4
Balance . . . 4

Muntins
Styles . . . 5
Hardware . . . 5

Screens
Hardware . . . 6
Latch and Clip . . . 6
Retaining Screw . . . 6
Plunger . . . 6
Cable . . . 6
Cloth . . . 6
Spline . . . 6

Double Glazing Panel (DGP) parts and accessories can be found in the Hinged Glass Panel parts catalog


Rev. 06/29/2024



	Part Number	Catalog Category	Catalog Subcategory
DH Upper Sash —Wood 1964 - 1983 —Clad 1970 - 1983 Note: Wood or Clad is no longer available.	No Longer Available		
DH Upper Sash Cladding - Set 1970 - 1983	No Longer Available		
DH Lower Sash —Wood 1964 - 1983 —Clad 1970 - 1983 Note: Wood or Clad is no longer available.	No Longer Available		
DH Lower Sash Cladding - Set 1970 - 1983	No Longer Available		
Pre 95 DH Lock, Strike, Shim and Screws - for IG Units DGP Package —Brass —Champagne 1991 - 1994 —Pella Gold 3/1990 - 12/1990 —White IG Package —Brass —Champagne —Pella Gold —White Replace all WD/CD design locks with this design, when replacing previous design locks, it is necessary to replace the strike also. 1964 - 1983	 No Longer Available 0DLQ0001 0DLQ0000 No Longer Available No Longer Available 0DLQ0005 0DLQ0004 No Longer Available	Window Hardware	Cam-Action Lock
Pre 95 DH Air Conditioning Lock, Strike, Shim and Screws - for IG Units –Pella Gold Replace all WD/CD design locks with this design, when replacing previous design locks, it is necessary to replace the strike also. 1964 - 1983	No Longer Available		
DH Sash Lift - Pella Gold –Pkg 1 Sash lift with screws 1964 - 1983	09470001	Sash/Panel Parts	Sash Lifts/ Covers/ Operators
DH AC Lock Key 1964 - 1983	0E0X0000	Window Hardware	Air Conditioner Lock



Previous Lock Design (No longer available)



Replacement Lock and Strike







	Part Number	Catalog Category	Catalog Subcategory
Sash Breather - (box 100) 1964 - 1983	No Longer Available		
DH Checkrail Felt Plug –Pkg 1 1964 - 1983	03LE0000	Frame Parts	Jamb/Dust Plugs
CD/WD Checkrail Weatherstrip (51") 1964 - 1983	No Longer Available		



	Part Number	Catalog Category	Catalog Subcategory
Top/Bottom Weatherstrip - (Pkg 10) Note: Replace previous Weatherstrip with this design. 1973 - 1987	No Longer Available (0D10)		
TD Lock Bumper - (box 100) 1964 - 1983	No Longer Available		
DH Bottom Jamb Liner Plug –(box 10) Note: This plug is used to replace previous design plugs. 3/1971 - 1983	0B550000	Frame Parts	Jamb/Dust Plugs
3/8" x 1/2" Foam Weatherstrip - (25 ft. roll) (Used as top jamb liner plug). Note: This material is used to replace previous design top jamb plug 3/1971 - 1983	No Longer Available		
WD/CD Mohair Stile Weatherstrip 1964 - 1983	No Longer Available		







	PQM location	Reqd. Info
DH Balance Spring 12/1969 - 1983* *1981 - 1992 can be used for pre-1983 vintage.	No Longer Available	
DH Jamb Liner 12/1969 - 1983	No Longer Available	
CD Contemporary Balance Cable	No Longer Available	




















	Part Number	Catalog Category	Catalog Subcategory
DH Double Click Spring Balance Box 1964 - 11/1969	No Longer Available		
DH Single Click Spring Balance Box 1964 - 11/1969	No Longer Available		
DH Balance Cord Terminal Pkg 1 or Pkg 20 1964 - 1983	No Longer Available		
DH Jamb Booster Spring –(Pkg 10) 10/1969 - 1983	0FAG0000	Frame Parts	Jamb Adjusters
DH Jamb Booster Spring 4/1964 - 9/1969	No Longer Available		
DH Balance Cord –(3,000 ft. roll) 1964 - 1983	No Longer Available	Double Hung Vent CD, MD	Obsolete DH Hardware
DH Balance Plate Assembly 12/1969 - 1983	No Longer Available	Double Hung Vent CD, MD	Obsolete DH Hardware
DH Balance Pulley Pkg 10 12/1969 - 1983	No Longer Available		
DH Balance Spring Jamb Attaching Bracket –(Pkg 2) 1964 - 1983	No Longer Available	Double Hung Vent CD, MD	Obsolete DH Hardware



	PQM location	Reqd. Info
Removable Traditional Muntin 1981 - 1992	No Longer Available	



Removable Diamond Grille Assembly 1967 - 1993	No Longer Available	



	Part Number	Catalog Category	Catalog Subcategory
Muntin Clip –(box 100) –(box 10) 1964 - 1983	 0CFP0000 0CFP0001	Grille Parts	Muntin Hardware



Classic Muntin Tack –(box 1,000) –(box 10) 1964 - 1983	 0B0K0000 0B0K0001	Grille Parts	Muntin Hardware



Bullet Catch - (box 100) 1967 - 1993	No longer available







Vinyl Screen Spline













	PQM location	Reqd. Info	
WD/CD Full Screen Note: Replace all previous vintage screen with this design. 1/1978 - 1983	Screen Service Items		
WD/CD Half Screen Assembly Note: Replace all previous vintage screen with this design 1/1978 - 1983	Screen Service Items		

	Part Number	Catalog Category	Catalog Subcategory
Vinyl Screen Spline –Gray (100 ft. roll) Note: Metal Spline for pre 1978 screens is not available. 1/1978 - 1983	06F10000	Screen Parts	Screen Spline
InView™ Fiberglass Screen Cloth –36" wide –48" wide 1/1978 - 1983	 052M0000 052M0001	Screen Parts	Screen Cloth
WD/CD Full Screen Hardware Package 1964 - 1983	No Longer Available (009Q)		
WD/CD Full Screen Latch and Clip –(box 20) 1/1965 - 1984	No Longer Available (0E88)		
Screen Retaining Screw –Box (100) 1/1970 - 1984	0E890000	Screen Parts	Screen Screws
WD/CD Half Screen Plunger –(box 20) 1/1965 - 1983	No Longer Available (06C3)		
DH Half Screen Safety Cable 1964 - 1983	051V0000	Screen Hardware and Parts	Double Hung Screen Parts
DH Half Screen Strike – Pkg (5)	No Longer Available		